


Workaround for programming 56F8323 in CodeWarrior v10.6 debugger

There is a known problem in CodeWarrior v10.6 debugger. After user creates a new bareboard project for 56F8323 in CW10.6 and starts debugging with USBTAP, but the debugger stops, and the debugger view shows "No source available for ".debug_frame + 0x000000A5 (0x00000000) (0x0000A5)()", just as below:



To resolve this problem, we need two steps:

- 1) Go to project folder, and open the file "MC56F8323.tcl" under "\Project_Settings\Debugger" subfolder, then add the line as below between "change x:0xF401 0x0000" and "change x:0xF401 0x0100" to unprotect boot sector:

change x:0xF411 0x0000

The picture as below shows the content in file "MC56F8323.tcl" after modification.

```


MC56F8323.tcl |
-----
1 radix x
2 config hexprefix 0x
3 config MemWidth 16
4 config MemAccess 16
5 config MemSwap off
6
7 #-----
8
9 # MC56F8323 initialization file for flash
10 # Freescale sample code
11
12 # Enable Reset.  GPIOD4 will be forced by the debugger
13 # GPIO D BASE + 3 is register address.  We need to set
14 # Content is 1 which means peripheral owns the pin.  No
15 # need to be set for this device in order to reset the
16 change x:0xF173 0x1000
17
18 # set Flash Clock Divider (write 0x27)
19 change x:0xF400 0x0A00
20
21 # unlock protection
22 change x:0xF401 0x0000
23
24 # unprotect
25 change x:0xF410 0x0000
26 change x:0xF411 0x0000
27
28 # unprotect data
29 change x:0xF401 0x0100
30 change x:0xF410 0x0000

```

It is recommended to make this modification in "MC56F8323.tcl" either which is under the CodeWarrior folder:

C:\Freescale\CW MCU v10.6\MCU\lib\wizard_data\DSC\DataBase\init_files

Because this file is copied into the project subfolder ("Project_Settings\Debugger") when user creates a new project for DSC from File menu->New->Barebaord project. User can find the path which saves the copied file as below:



2) Go to CodeWarrior v10.6 installation folder, usually is below:

C:\Freescale\CW MCU
v10.6\MCU\bin\plugins\support\Products\ProductData\DSCFPDevices.mwpdb\FP

And open the file "MC56F8323_P_FLASH.xml", then change the value in line13 from:

```
<skip_bytes>0x18000</skip_bytes>
```

to :

```
<skip_bytes>0x1C000</skip_bytes>
```

This is a gap to the boot sector of the flash memory.

The picture as below shows the content in file "MC56F8323.tcl" after modification.

```

1 <?xml version="1.0" encoding="UTF-8"?>
2 <device-file>
3 <device>
4 <content>
5     <name>MC56F8323_P_FLASH</name>
6     <manufacturerid>0xFFFF</manufacturerid>
7     <chiperase>true</chiperase>
8     <memory_space>0</memory_space>
9     <access_type>WORD</access_type>
10    <sectors>
11        <sectorcount>32</sectorcount>
12        <sectorsize>0x200</sectorsize>
13        <skip_bytes>0x1000</skip_bytes>
14        <sectorcount>16</sectorcount>
15        <sectormem>boot</sectormem>
16        <sectorsize>0x100</sectorsize>
17    </sectors>
18    <protecttype>dsc_hfm_program_32k_boot_8k</protecttype>
19    <flash_config_base>0x3FF7</flash_config_base>
20    <clock_div>0xA0</clock_div>
21    <flash_module_base>0xF400</flash_module_base>
22    <buffer_start>0x2FC00</buffer_start>
23    <buffer_size>0x400</buffer_size>
24    <third_party_support>
25        <workspace_start>0x2F800</workspace_start>
26        <workspace_size>0x200</workspace_size>
27    </third_party_support>
28    <organizationcount>1</organizationcount>
29    <organization>
30        <name>68kx16x1</name>
31        <id>0xFFFF</id>
32        <begin_address>0x000000</begin_address>
33        <end_address>0x021000</end_address>
..

```

3) When CodeWarrior launches, it creates one database, which includes all xml config files from the {CW home directory}\MCU\bin\plugins\support\Products\ProductData. It's name is chameleon_toc.sqlite. If this file already exists, is not enough to fix MC56F8323_P_FLASH.xml. User have to delete C:\Freescale\CW MCU v10.6\MCU\bin\plugins\support\Products\ProductData\chameleon_toc.sqlite (if it exists)

After these modifications, the debugger become work well with USBTAP and MC56F8323.

The attached two files are the modified "MC56F8323.tcl" and "MC56F8323_P_FLASH.xml". User can put them under the subfolder below to replace the old ones:

C:\Freescale\CW MCU v10.6\MCU\lib\wizard_data\DSC\DataBase\init_files

and

C:\Freescale\CW MCU

v10.6\MCU\bin\plugins\support\Products\ProductData\DSCFPDevices.mwpdb\FP

This problem will be fixed in further update. Before it, user can use the workaround in above to resolve the problem.