POR is manually operated, when sytem is power up POR is low and it become high after 176ms after all power rails are ON. But in these case systoem is not booting up. We have to give second POR manully and then system reboots.