I am trying to play with NXP BLE Kit to get acquinted with NXP BLE Stack. I am facing some errors working with example project, please pass on my email to application engineer who can guide me resolving these errors.

NXP

Problem Occurred

'Launching qn908xcdk_wireless_examples_bluetooth_heart_rate_sensor_f reertos LinkServer Debug' has encountered a problem.

Error in final launch sequence

[OK] [<< Details]

Error in final launch sequence
    Failed to execute MI command:
-target-select extended-remote | crt_emu_cm_redlink
-msg-port=56002 -g -mi -2 -pQN908XC -vendor=NXP
--connectscript=RunBootRomConnect.scp
--resetscript=qn908xreset.scp --reset= -ProbeHandle=1
-CoreIndex=0 -cache=disable --flash-driver= -x
C:/Users/abx/Documents/MCUXpressoIDE_10.3.1_2233/workspa
ce/qn908xcdk_wireless_examples_bluetooth_heart_rate_sensor_fr
eertos/Debug --flash-dir
C:/Users/abx/Documents/MCUXpressoIDE_10.3.1_2233/workspa
ce/.mcuxpressoide_packages_support/QN908XC_support/Flash
--telnet 3330
Error message from debugger back end:
Remote communication error. Target disconnected.: Success.

LinkServer

17^error,msg="Remote communication error. Target disconnected.: Success."

Reason:
Failed to execute MI command:
-target-select extended-remote | crt_emu_cm_redlink -msg-port=56002 -g -mi -2
-pQN908XC -vendor=NXP --connectscript=RunBootRomConnect.scp
--resetscript=qn908xreset.scp --reset= -ProbeHandle=1 -CoreIndex=0 -cache=disable
--flash-driver= -x
C:/Users/abx/Documents/MCUXpressoIDE_10.3.1_2233/workspace/qn908xcdk_wireless_exa
mples_bluetooth_heart_rate_sensor_freertos/Debug --flash-dir
C:/Users/abx/Documents/MCUXpressoIDE_10.3.1_2233/workspace/.mcuxpressoide_packag
es_support/QN908XC_support/Flash --telnet 3330
Error message from debugger back end:
Remote communication error. Target disconnected.: Success.

[OK]

gger Console ⬤ Instruction Trace ⬛O Power Measurement Tool ⬛ SWO Trace Config

ebug messages
 - crt_emu_cm_redlink build 760)
.3.1_2233/workspace/qn908xcdk_wireless_examples_bluetooth_heart_rate_sensor_f

gave 'Ee(42). Could not connect to core.'
gave 'Ee(42). Could not connect to core.'
gave 'Ee(42). Could not connect to core.'
s) - Ee(42). Could not connect to core.

Updates Available x

Updates are available for your software
Click to review and install updates.

You will be reminded in 4 Hours.
Set reminder preferences