

2.2M Resistor from CPU_XTAL1 to GND is required to correct a known SMT124 slow starting issue present iMX6 part. Please refer to the iMX6 Processor Errata, issue # ER000777

