

### **SDK Migration**

Lu Lin

APR.2015



#### External Use









## Agenda

- Overview
- Description of Process
- Q&A





#### **Overview**

- SDK package may not cover all Kinetis devices when released, but some customers may want to use our SDK on their specified Kinetis silicon that is not supported by current SDK.
- This presentation will discuss about how to do to make a successful port from a supported device to a non-supported device.
- Take K60D10 and TWR-K60D100M board as example based on SDK1.2 release package.
- The chip of TWR-K60D100M is MK60DN512VMD10 and it belongs to MK60DN512xxx10 series.
  - Assuming that SDK1.2 doesn't support K60D10 and can be found that the most similar device with K60 in SDK1.2 is K64F120M.





# Description of Process

there are four main steps to be porting.


- Create the device specific files
- **Build the Platform Library**
- Create the Board configuration files
- Modify the Projects








- The device specific files include register definition files, feature definition files, startup files, linker files and other such as specified clock, sim files.
- Create a new directory named "MK60D10" under path sdk\_install\_folder\platform\devices\, then copy all files under path sdk\_install\_folder\platform\devices\ \MK64F12 to path sdk\_install\_folder\platform\devices\ MK60D10.
- Modify the name of file from "MK64F12" to "MK60D10".







- The directory "include" includes device specific register definition, feature definition and so on
- These files should be modified according to the datasheet and reference manual of K60D10.



```
#elif defined(CPU MK60DN512VMD10)
 · · · #define · K60D10 SERIES
  · · /* · CMSIS-style · register · definitions · */
    #include 'MK60D10/include/MK60D10.h"
    /* Extension register definitions */
    #include "MK60D10/include/MK60D10 extension.h"
    /* CPU specific feature definitions */
    #include "MK60D10/include/MK60D10 features.h"
```

 Then Add these header files into the common file "fsl\_device\_registers.h" which located at \platform\devices.






- The directory "linker" includes device specific link file for each tool chain, such as IAR, Keil and so on.
- These files should be modified according to the memory map of K60D10, take IAR as example:







- The directory "startup" includes device specific startup files for each tool chain, such as IAR, Keil and so on.
- These files should be modified according to the reference manual of K60D10 and main modification is clock setup and interrupt vector table.



 Other driver/hal/system device specific files should be created, for example, under path sdk\_install\_folder\platform\system\src\clock\, each device has its own clock definition files, Copy \MK64F12 to \MK60D10 and modify these files for K60D10.



Then add clock content of K60D10 into common file "fsl\_clock\_manager.h" which located at \platform\system\inc.

```
#elif (defined(K60D10 SERIES))
···/* Clock System Level API header file */
   #include "../src/clock/MK60D10/fsl clock MK60D10.h"
```





 under path sdk\_install\_folder\platform\hal\src\sim\, each device has its own SIM definition files, Copy \MK64F12 to \MK60D10 and modify these files for K60D10.



Then add SIM content of K60D10 into common file "fsl\_sim\_hal.h" which is located at sdk\_install\_folder\platform\hal\inc


```
#elif (defined(K60D10 SERIES))
/* Clock System Level API header file */
#include "../src/sim/MK60D10/fsl sim hal MK60D10.h"
```





#### **Build the Platform Library**


- Under directory sdk\_install\_folder\lib, there are platform library's project files for each tool chain.
- Take IAR project files of ksdk\_platform\_lib as example.Copy \lib\ksdk\_platform\_lib\iar\K64F12 to \lib\ksdk\_platform\_lib\iar\K60D10. Add modules that K60D10 had and K64F12 didn't have into the library and remove modules that K60D10 didn't have and K64F12 had.
- Then modify the project options.







### **Build the Platform Library**








### **Create the Board configuration files**


- The board configuration files are located at sdk\_install\_folder\examples. Copy \twrk64f120m to \twrk60d100m, and board configuration files are board.c, board.h, gpio\_pins.c, gpio\_pins.h, pin\_mux.c and pin\_mux.h
- Modify these files according to schematic and reference manual.







- For SDK1.2, the demos are located at \examples\twrk60d100m\demo\_apps and \examples\twrk60d100m\driver\_examples
- Take hello\_world demo as example.




Hardware\_init.c should be modified according to schematic and reference manual.






 Take IAR project as example, project option and platform library project included should be modified.



- The included platform library should be changed to the library for K60D10.
- And the startup file included should be changed to files for MK60D10.












Then change the linker file and link library.













www.Freescale.com