


Inside Config Tool V3.0 offline



Without internet and can't see the SDK file content

Create a new configuration

Clone an SDK example

Select an SDK example

Select version

Name your configuration

< Back Next > Finish Cancel

Connect internet, close the Config tool and re-launch application, now can see the SDK content

